222 #14530952 92 ID:88078207
QL 84.2 .L35 no.222 c.3 TN:222

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

TECHNICAL NOTE

Filing Code 9147
Date Issued March 20, 196

Bureau of Land Management U.S. DEPARTMENT OF THE INTERIOR

SNOWMOBILE VARIABLE PITCH SHEAVE DRIVE BELTS

If you have had replacement problems, try a Dayton Belt. These Dayco cut V-belts give high traction and are cut to an accurate angle. Both features are required for satisfactory performance. These belts can be used for any replacements. If local dealers do not have them, contact Premiere Distributors in Denver, Telephone No. 936-3433 (Area Code 303).

Stanley E. Hill
Denver Service Center

BLM Library
Denver Federal Center
Bldg. 85, OC-521
P.O. Box 25047
Denver, CO 80225

FOR ADDITIONAL COPIES WRITE TO DIRECTOR, PORTLAND SERVICE CENTER, BOX 3861, PORTLAND, ORE., 97208